



Certificate MX06/1025

The management system of

MEXQ / Calidad del Norte, S.C.

Av. De la Convención Norte No. 1302 Local 101-B, Fracc. Circunvalación Norte,
Aguascalientes, Aguascalientes. C.P. 20020, México.

has been assessed and certified as meeting the requirements of

ISO 9001:2015

For the following activities

**Inspection, Selection and/or Rework of defective parts In
Automotive Industry and General Manufacturing.**

**Inspección, Selección y/o Retrabajo de productos defectuosos
en la Industria Automotriz y de Manufactura en General**

This certificate is valid from 17 April 2021 until 27 February 2024
and remains valid subject to satisfactory surveillance audits.
Recertification audit due a minimum of 60 days before the expiration date.
Issue 7. Certified since 28 February 2003



Authorised by

SGS United Kingdom Ltd
Rossmore Business Park, Ellesmere Port, Cheshire, CH65 3EN, UK
t +44 (0)151 350-6666 f +44 (0)151 350-6600 www.sgs.com

HC: SGS 9001 2015 0818

Page 1 of 1



0005



This document is a Web version of SGS certificate for electronic use exclusively. It shall only be available by clicking on SGS Certification Mark which has been posted on Your website. It shall not be printed in anyway. This document is copyright protected. No content or appearance may be reproduced without the express written permission of SGS. Any misuse, alteration, forgery or falsification is unlawful.